Location: FRASER OIL INC GALATA 30342 US Hwy 2 & Galata Rd Galata, MT 59444 Toole

System Facility ID:51-02311

Facility Code: 29035 Last Inspected On: 11/16/2023 Operating Permit Renewal Date: 03/17/2027

#### Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Fraser Oil Inc

(406) 292-3833

Tank/Piping CP

Line Tightness

Test Date

Test Date

11/16/2023

04/29/2021

12/11/2008

Operator Contact: Cory Fraser

frasfuel@yahoo.com

Vapor Recovery No

No

**Energy Act** 

Owner/Opera	ator: Fraser	Oil Inc		(406)	) 292-3833						
		ory Fraser, UST Class ory Fraser, UST Class	·					frasfuel@y frasfuel@y			
Tank Code	03	Tank Age	33	Tank Installed Date	10/01/1992	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1126	Spill Test Date	11/16/2023	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	11/03/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	1000	ATG Test Date	11/16/2023	Line Tightness Test Date	12/11/2008	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	11/16/2023			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	04	Tank Age	33	Tank Installed Date	10/01/1992	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1127	Spill Test Date	11/16/2023	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic

Primary Tank

Leak Detection

Secondary Tank

Leak Detection

ATG Type

Diesel

1000

PLLD Test Date

ATG Test Date

Overfill Test Date 11/16/2023

Product

Capacity

- - - - -

**Primary Pipe** 

Secondary Pipe

Detection

Detection

Automatic Tank

Gilbarco-Veeder

Gauging 0.2

Root/TLS-350/Gilbarco EMC

Location: BTI CONOCO Hwy 2 Shelby, MT 59474 Toole

System Facility ID:51-08629

Facility Code: 29119 Last Inspected On: 07/28/2023 Operating Permit Renewal Date: 11/27/2026

#### Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Ben Taylor Inc;Pat Simons;Simons Petroleum Inc;Unclaimed bti@3rivers.net;simonspt@3rivers.net (406) 434-2431 Operator Contact: David Emerson; City Service Valcon LLC (406) 294-0865 david.emerson@cityservicevalcon.com;tamara.noble@cityservice valcon.com Owner/Operator: Ben Taylor Inc bti@3rivers.net David Emerson, UST Class A Operator tamara.noble@cityservicevalcon.com David Emerson, UST Class B Operator tamara.noble@cityservicevalcon.com **Tank Code** 09 Tank Installed Fiberglass **Piping Material** Tank Age 20 05/27/2005 Tank Material Flexible Plastic **Overfill Types Ball Float Valve** Reinforced Plastic Date **Piping Installed** Piping Tank **Tag Number** 5012 Spill Test Date 01/25/2024 **Double Walled** AST No Date Construction Construction Sump Tightness Catastrophic L.D Electronic Line Currently in **Tank Status** MLLD Test Date **Piping Type CP Met Types** Pressurized Non-corrodible Type 3.0 Use **Test Date** Leak Detector Tank/Piping CP **Primary Tank** Automatic Tank **Primary Pipe** ELLD 0.2 Product Gasoline PLLD Test Date Vapor Recovery No Test Date Leak Detection Gauging 0.2 Detection Continuous Line Tightness Secondary Tank **Secondary Pipe** 6000 **ATG Test Date** 07/27/2023 Interstitial No Capacity Energy Act Leak Detection **Test Date** Detection Monitoring Gilbarco-Veeder Overfill Test Date 07/27/2023 ATG Type Root/TLS-350/Gilbarco EMC Tank Code 08 Fiberglass Tank Installed Tank Age 20 05/27/2005 Tank Material **Piping Material** Flexible Plastic **Overfill Types Ball Float Valve** Reinforced Plastic Date **Piping Installed** Tank Piping **Tag Number** 5013 **Spill Test Date** 01/25/2024 **Double Walled** AST No Date Construction Construction Sump Tightness Catastrophic L.D Electronic Line Currently in **MLLD Test Date Tank Status Piping Type CP Met Types** Pressurized Non-corrodible Test Date Type 3.0 Leak Detector Use Tank/Piping CP **Primary Pipe Primary Tank** Automatic Tank Product Diesel **PLLD Test Date** ELLD 0.2 Vapor Recovery No Leak Detection Test Date Gauging 0.2 Detection Continuous Line Tightness Secondary Tank Secondary Pipe 5000 07/27/2023 Capacity ATG Test Date Interstitial **Energy Act** No Leak Detection Test Date Detection Monitoring Gilbarco-Veeder Overfill Test Date 07/27/2023 ATG Type Root/TLS-350/Gilbarco EMC

Tank Code	07	Tank Age	20	Tank Installed Date	05/27/2005	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	5014	Spill Test Date	01/25/2024	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date	07/27/2023	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/27/2023			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	10	Tank Age	20	Tank Installed Date	05/27/2005	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	5015	Spill Test Date	01/25/2024	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	5000	ATG Test Date	07/27/2023	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/27/2023			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Location: H AND R INC 6 101 E Main St Shelby, MT 59474-2127 Toole

System Facility ID:51-06113

Facility Code: 29092 Last Inspected On: 11/15/2023 Operating Permit Renewal Date: 01/08/2027

### Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operate	or Contact: Sing	ih Inc			(406) 868-2062			inder40	30@yahoo.com		
Operate	or Contact: Hari	nder Singh;Singh Inc			(406) 868-2062;(4	406) 868-2062		inder40	30@yahoo.com;ind	er4030@yahoo.cor	n
Owner/Oper	ator: Singh I	nc		(406	) 868-2062			inder4030@	)yahoo.com		
	Fra	ank Kruse, UST Class ank Kruse, UST Class rrinder Singh, UST Cla	B Operator					wfkruse79	@yahoo.com @yahoo.com @yahoo.com		
Tank Code	Tank Age     36     Date       Number     426     Spill Test Date     07/13/2023     Piping Installed					Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	426	Spill Test Date	07/13/2023	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/12/2021	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date	07/31/2023	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/06/2024			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	07	Tank Age	36	Tank Installed Date	08/16/1989	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	427	Spill Test Date	07/13/2023	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/12/2021	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date	07/31/2023	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

		Overfill Test Date	06/06/2024			АТG Туре	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	08	Tank Age	36	Tank Installed Date	08/16/1989	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	428	Spill Test Date	12/08/2021	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	03/12/2021	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date	07/31/2023	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/06/2024			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	09	Tank Age	36	Tank Installed Date	08/16/1989	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	429	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	03/12/2021	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date	07/31/2023	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/06/2024			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				

Location: NOONS FOOD STORE 602 W Roosevelt Hwy 2 Shelby, MT 59474 Toole

System Facility ID:51-00104

Facility Code: 28986 Last Inspected On: 04/24/2025 Operating Permit Renewal Date: 04/18/2028

### Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operat	or Contact: MCI	P INC			(406) 434-5882			mcpshe	elby@gmail.com		
Operat	or Contact: Mar	njit Maan			(209) 647-8034			mcpshe	lby@gmail.com		
Owner/Ope	rator: MCP IN	1C		(406	) 434-5882			mcpshelby(	@gmail.com		
		anjit Maan, UST Class anjit Maan, UST Class	•						@gmail.com @gmail.com		
Fank Code	02	Tank Age	53	Tank Installed Date	02/18/1972	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
ag Number 3557 Spill Test Date 04/24/2025		Piping Installed Date	09/21/2006	Tank Construction		Piping Construction	Single Walled	AST	No		
Currently in Use         MLLD Test Date         Sump Tightness Test Date					Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current	
Product	Gasoline	PLLD Test Date	04/24/2025	Tank/Piping CP Test Date	11/03/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	04/24/2025	Line Tightness Test Date	11/12/2024	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	04/24/2025			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Fank Code	01	Tank Age	53	Tank Installed Date	02/18/1972	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
ag Number	4382	Spill Test Date	05/07/2025	Piping Installed Date	09/21/2006	Tank Construction		Piping Construction	Single Walled	AST	No
Fank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product Cosoline PLLD Test Date 04/24/2025 Tank/		Tank/Piping CP Test Date	11/03/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No		
Capacity	10000	ATG Test Date	04/24/2025	Line Tightness Test Date	11/12/2024	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
Overfill Test Date 04/24/2025						ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	03	Tank Age	53	Tank Installed Date	02/18/1972	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve

Tag Number	4383	Spill Test Date	04/24/2025	Piping Installed Date	09/21/2006	Tank Construction		Piping Construction	Single Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	04/24/2025	Tank/Piping CP Test Date	11/03/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	04/24/2025	Line Tightness Test Date	11/16/2024	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	04/24/2025			АТG Туре	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Location: TOWN PUMP INC SHELBY 1350 W Roosevelt Hwy Shelby, MT 59474 Toole

System Facility ID:51-09749

Facility Code: 29136 Last Inspected On: 09/08/2024 Operating Permit Renewal Date: 08/06/2027

#### Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Shelby 1 Town Pump LLC (406) 497-6700 environmental@townpump.com **Operator Contact:** Trent Biggers Trentb@townpump.com Owner/Operator: Shelby 1 Town Pump LLC (406) 497-6700 environmental@townpump.com Trent Biggers, UST Class A Operator Trentb@townpump.com Trent Biggers, UST Class A Operator Trentb@townpump.com Trent Biggers, UST Class B Global Operator Trentb@townpump.com Trent Biggers, UST Class B Global Operator Trentb@townpump.com Tank Code 01 Tank Installed Cathodically Fiberglass Tank Age 37 09/07/1988 **Tank Material Piping Material Overfill Types Ball Float Valve** Protected Steel **Reinforced Plastic** Date **Piping Installed** Tank Piping 2657 **Spill Test Date** 09/20/2023 AST Tag Number Double Walled No Construction Construction Date Catastrophic L.D Currently in Sump Tightness Mechanical Line 03/14/2024 09/20/2023 **Piping Type** Tank Status MLLD Test Date Pressurized **CP Met Types** Galvanic Use **Test Date** Type 3.0 Leak Detector Statistical Statistical Tank/Piping CP **Primary Tank Primary Pipe** 09/20/2023 Gasoline **PLLD Test Date** Inventory Inventory Vapor Recovery Product Yes Test Date Leak Detection Detection Reconciliation Reconciliation Continuous Line Tightness Secondary Tank Secondary Pipe 12000 **ATG Test Date** 03/14/2024 Interstitial No Capacity Energy Act Leak Detection Detection Test Date Monitoring Gilbarco-Veeder ATG Type Overfill Test Date 09/20/2023 Root/TLS-450PLUS **Tank Code** 02 Tank Installed Cathodically 37 **Flexible Plastic** Flapper Valve Tank Age 09/07/1988 **Tank Material Piping Material Overfill Types** Protected Steel Date **Piping Installed** Tank Piping **Spill Test Date Tag Number** 2658 09/20/2023 **Double Walled** AST No Date Construction Construction Currently in Sump Tightness Catastrophic L.D Mechanical Line 03/14/2024 09/20/2023 **Piping Type Tank Status** MLLD Test Date **CP Met Types** Pressurized Galvanic Use **Test Date** Type 3.0 Leak Detector Statistical Statistical Tank/Piping CP **Primary Tank Primary Pipe** Product Diesel PLLD Test Date 09/20/2023 Inventory Inventory Vapor Recovery No Test Date Leak Detection Detection Reconciliation Reconciliation

Capacity	12000	ATG Test Date	03/14/2024	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	09/20/2023			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	03	Tank Age	37	Tank Installed Date	09/07/1988	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;Flapper Valve
Tag Number	2659	Spill Test Date	09/20/2023	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/14/2024	Sump Tightness Test Date	09/20/2023	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	09/20/2023	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/14/2024	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	09/20/2023			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	07	Tank Age	33	Tank Installed Date	08/01/1992	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2663	Spill Test Date	01/23/2024	Piping Installed Date	10/22/2012	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/14/2024	Sump Tightness Test Date	09/20/2023	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	09/20/2023	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/14/2024	Line Tightness Test Date	04/01/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	09/20/2023			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	08	Tank Age	26	Tank Installed Date	07/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4248	Spill Test Date	09/20/2023	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/14/2024	Sump Tightness Test Date	09/20/2023	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	11/27/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No

Capacity	8000	ATG Test Date	03/14/2024	Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	09/20/2023			АТG Туре	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	04	Tank Age	37	Tank Installed Date	09/07/1988	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4291	Spill Test Date	09/20/2023	Piping Installed Date	10/22/2012	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/14/2024	Sump Tightness Test Date	09/20/2023	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	09/20/2023	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/14/2024	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date	09/20/2023			АТС Туре	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	05	Tank Age	37	Tank Installed Date	09/07/1988	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4292	Spill Test Date	09/20/2023	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/14/2024	Sump Tightness Test Date	09/20/2023	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	09/20/2023	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/14/2024	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	09/20/2023			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	06	Tank Age	33	Tank Installed Date	08/01/1992	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	4293	Spill Test Date	01/03/2024	Piping Installed Date	10/22/2012	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/14/2024	Sump Tightness Test Date	09/20/2023	Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	11/27/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/14/2024	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

		Overfill Test Date	09/20/2023			АТG Туре	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	09	Tank Age	24	Tank Installed Date	10/01/2001	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4413	Spill Test Date	09/20/2023	Piping Installed Date	10/22/2012	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/14/2024	Sump Tightness Test Date	09/20/2023	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	11/27/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	20000	ATG Test Date	03/14/2024	Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date	09/20/2023			ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	10	Tank Age	13	Tank Installed Date	09/01/2012	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	5416	Spill Test Date		Piping Installed Date	10/02/2012	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	10/18/2012	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	DEF (Not Regulated)	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Approved Remote Monitoring;Autom atic Tank Gauging 0.2	Primary Pipe Detection	Approved Remote Monitoring;Continu ous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date	04/25/2023	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450PLUS				
Tank Code	11	Tank Age	0	Tank Installed Date		Tank Material	Other	Piping Material	Steel	Overfill Types	
Tag Number	5862	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Permanently Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0		Piping Type	Not Listed	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Not Listed	Primary Pipe Detection	Not Listed	Vapor Recovery	No
Capacity	150	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Not Listed	Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	12	Tank Age	0	Tank Installed Date		Tank Material	Other	Piping Material	Steel	Overfill Types	

Tag Number	5874	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Fank Status	Permanently Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0		Piping Type	Not Listed	CP Met Types	
Product		PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Not Listed	Primary Pipe Detection	Not Listed	Vapor Recovery	No
Capacity	150	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Not Listed	Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	13	Tank Age	0	Tank Installed Date		Tank Material	Other	Piping Material	Steel	Overfill Types	
Tag Number	5890	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Permanently Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0		Piping Type	Not Listed	CP Met Types	[
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Not Listed	Primary Pipe Detection	Not Listed	Vapor Recovery	No
Capacity	150	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Not Listed	Energy Act	No
		Overfill Test Date				ATG Type					
Fank Code	19	Tank Age	1	Tank Installed Date	04/30/2024	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	6239	Spill Test Date	05/15/2024	Piping Installed Date	05/15/2024	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/15/2024	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/29/2024	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	8000	ATG Test Date	05/15/2024	Line Tightness Test Date	05/15/2024	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	05/15/2024			ATG Type					

Location: TAYLORS BULK PLANT 55 Railroad Ave Sunburst, MT 59482 Toole

System Facility ID:51-02025

Facility Code: 29031 Last Inspected On: 04/08/2022 Operating Permit Renewal Date: 06/22/2025

#### Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Ben Taylor Inc bti@3rivers.net Operator Contact: Scott Curry scott.curry@btimontana.com Brian Robertson, UST Class B Operator brian@kwsunburst.com Brian Robertson, UST Class B Operator brian@kwsunburst.com Dan Gliko, UST Class B Operator dglikojr@gmail.com Dan Gliko, UST Class B Operator dglikojr@gmail.com Scott Curry, UST Class A Operator scott.curry@btimontana.com Tank Code S6 Tank Installed **Flexible Plastic** Tank Age 26 08/31/1999 Tank Material Unknown **Piping Material Overfill Types** Date **Piping Installed** Tank Piping **Tag Number** 4137 Spill Test Date **Double Walled** AST Yes Date Construction Construction Continuous Interstitial Permanently Sump Tightness Catastrophic L.D **Tank Status MLLD Test Date** 04/08/2022 04/20/2016 Monitoring;Mecha Piping Type Pressurized **CP Met Types** Out of Use Test Date Type 3.0 nical Line Leak Detector **Primary Pipe** Tank/Piping CP **Primary Tank** MLLD Line Product Gasoline PLLD Test Date Vapor Recovery No Test Date Leak Detection Detection **Tightness Testing** Continuous **Secondary Pipe** Line Tightness Secondary Tank 24000 **ATG Test Date** 04/08/2022 Interstitial Capacity Energy Act No Leak Detection Test Date Detection Monitoring **Overfill Test Date** ATG Type S7 Tank Code Tank Installed **Tank Age** 26 08/31/1999 Tank Material **Piping Material** Flexible Plastic **Overfill Types** Unknown Date **Piping Installed** Piping Tank 4138 **Spill Test Date** AST Tag Number **Double Walled** Yes Date Construction Construction Continuous Interstitial Permanently Sump Tightness Catastrophic L.D **Tank Status** MLLD Test Date 04/08/2022 04/20/2016 Monitoring;Mecha Piping Type Pressurized **CP Met Types** Out of Use Test Date Type 3.0 nical Line Leak Detector Tank/Piping CP **Primary Tank Primary Pipe** MLLD Line Gasoline No Product PLLD Test Date Vapor Recovery Test Date Detection Leak Detection Tightness Testing

Report Created: 5/21/2025

Page [13] of [17]

Capacity	40000	ATG Test Date		Line Tightness Test Date	04/08/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S8	Tank Age	26	Tank Installed Date	08/31/1999	Tank Material	Unknown	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	4139	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Permanently Out of Use	MLLD Test Date	04/08/2022	Sump Tightness Test Date	04/20/2016	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	40000	ATG Test Date		Line Tightness Test Date	04/08/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S9	Tank Age	26	Tank Installed Date	08/31/1999	Tank Material	Unknown	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	4140	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Permanently Out of Use	MLLD Test Date	04/08/2022	Sump Tightness Test Date	04/20/2016	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	40000	ATG Test Date		Line Tightness Test Date	04/08/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	S10	Tank Age	26	Tank Installed Date	08/31/1999	Tank Material	Unknown	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	4161	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Permanently Out of Use	MLLD Test Date	04/08/2022	Sump Tightness Test Date	04/20/2016	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	3000	ATG Test Date		Line Tightness Test Date	04/08/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Page [14] of [17]

Overfill Test Date	ATC Type		
Overnin rest Date	AIGType		
	51		

### Facility Summary in Toole County in the City of Sweet Grass

Location: DUTY FREE AMERICAS Facility Code: 29016 Last Inspected On: 08/03/2023 60 3rd Ave Sweet Grass, MT 59484-0249 Toole System Facility ID:51-01377 Operating Permit Renewal Date: 09/06/2026 Note: Inspection is due 90 days before the Operating Permit Renewal Date. Owner Operator Contact: Duty Free America's Hollywood (954) 986-7700 **Operator Contact:** Chad Underdal cunderdal@dutyfreeamericas.com Owner/Operator: Duty Free America's Hollywood (954) 986-7700 Chad Underdal, UST Class A Operator cunderdal@dutyfreeamericas.com Chad Underdal, UST Class B Operator cunderdal@dutyfreeamericas.com Kelsey Burley, UST Class B Operator store203@dutyfreeamericas.com 03 Tank Code Tank Installed Cathodically Fiberglass Tank Age 35 01/01/1990 **Tank Material Piping Material Overfill Types High Level Alarm** Protected Steel Reinforced Plastic Date **Piping Installed** Tank Piping **Tag Number** 871 Spill Test Date None AST No Construction Date Construction Sump Tightness Catastrophic L.D Electronic Line Currently in MLLD Test Date **Tank Status Piping Type** Pressurized **CP Met Types** Galvanic Use Test Date Type 3.0 Leak Detector Tank/Piping CP **Primary Tank Primary Pipe** Automatic Tank Product Gasoline PLLD Test Date 04/17/2023 05/20/2024 **ELLD 0.2** Vapor Recovery No **Test Date** Leak Detection Gauging 0.2 Detection Line Tightness Secondary Tank Secondary Pipe Capacity 15000 **ATG Test Date** 04/17/2023 **Energy Act** No **Test Date** Leak Detection Detection Gilbarco-Veeder Overfill Test Date 04/17/2023 Root/TLS-ATG Type 350/Gilbarco EMC Cathodically Protected Steel **Tank Code** 04 Tank Installed Fiberglass 35 01/01/1990 Tank Material **Piping Material** Tank Age **Overfill Types** High Level Alarm Reinforced Plastic Date **Piping Installed** Tank Piping 872 02/19/2024 Tag Number Spill Test Date None AST No Construction Construction Date Sump Tightness Catastrophic L.D Electronic Line Currently in **Tank Status MLLD Test Date Piping Type** Pressurized **CP Met Types** Galvanic Use **Test Date** Type 3.0 Leak Detector Tank/Piping CP **Primary Tank** Automatic Tank **Primary Pipe** 04/17/2023 10/10/2017 ELLD 0.2 Product Gasoline PLLD Test Date Vapor Recovery No Leak Detection Detection **Test Date** Gauging 0.2 Line Tightness Secondary Tank **Secondary Pipe** 04/17/2023 15000 **ATG Test Date** Capacity Energy Act No Leak Detection **Test Date** Detection Gilbarco-Veeder Overfill Test Date 02/19/2024 ATG Type Root/TLS-350/Gilbarco EMC

# Facility Summary in Toole County in the City of Sweet Grass

Location: SHORYA ENTERPRISES 510 2nd St Sweet Grass, MT 59484 Toole

System Facility ID:51-12405

Facility Code: 29154Last Inspected On: 03/18/2025Operating Permit Renewal Date: 03/27/2027

### Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Sunita Toora Operator Contact: Samantha Carney;Sunita Toora			(408) 449-9333				pardeep.k51@yahoo.com				
				(406) 505-0320;(4	408) 449-9333	pardeep.k51@yahoo.com					
Owner/Operator: Sunita Toora			(408)	(408) 449-9333			pardeep.k51@yahoo.com				
Samantha Carney, UST Class A Opera Samantha Carney, UST Class B Opera Sunita Toora, UST Class A Operator Sunita Toora, UST Class B Operator			Class B Operat s A Operator				pardeep.k51@yahoo.com pardeep.k51@yahoo.com pardeep.k51@yahoo.com pardeep.k51@yahoo.com				
Tank Code	01			Tank Installed			Fiboralooo				· · · · · · · · · · · · · · · · · · ·
	UI	Tank Age	34	Date	06/25/1991	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	2718	Spill Test Date	08/06/2024	Piping Installed Date		Tank Construction		Piping Construction	Single Walled	AST	No
Fank Status	Currently in Use	MLLD Test Date	04/04/2024	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	04/04/2024	Line Tightness Test Date	04/04/2024	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	04/04/2024			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	34	Tank Installed Date	06/25/1991	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	2719	Spill Test Date	08/06/2024	Piping Installed Date		Tank Construction		Piping Construction	Single Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	04/04/2024	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	04/04/2024	Line Tightness Test Date	04/04/2024	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	04/04/2024			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				